

Subject

# Corolla Cross Right and Left Roof Rail Loose to Roof Panel

Market

USA

Service Category

Vehicle Exterior

Section

Exterior Panels/Trim

Applicability

22-24MY Corolla Cross/Corolla Cross HV

## APPLICABLE VEHICLES

2023-2024	Corolla Cross HV	2022-2024	Corolla Cross
-----------	------------------	-----------	---------------

## CONDITION

Some 2022-2024 model year Corolla Cross and Corolla Cross HV may exhibit a loose roof rail condition at the front or rear roof rail (see image 1).



## RECOMMENDATIONS

Confirm the condition exists on 1 or both roof rails. Replace roof rails per the following part numbers:

- Rack Assy, Roof, RH (62403-0A042)
- Rack Assy, Roof, LH (62404-0A042)

Refer to TIS, applicable model and model year Repair Manual to fix this condition.

Note: TSB to be released for double-sided tape kit.

## LINK REFERENCES

This Tech Tip does not contain any link references