

Subject

Oil Leak from the Engine Oil Level Sensor Area

Market

USA

Service Category

Engine/Hybrid System

Section

Lubrication

Applicability

Corolla, Corolla Cross, Corolla HB Sedan

APPLICABLE VEHICLES

2022-2024	Corolla Cross	2020-2024	Corolla Hatchback
2020-2024	Corolla		

CONDITION

Some technicians may report an engine oil leak from the Engine Oil Level Sensor area (Fig. 1).




Fig. 1

RECOMMENDATIONS

Please report oil leaks via a Dealership Product Report (DPR) and clarify the source of the leak, by including the following information:

1. Photos of the leaking area before and after being cleaned off (Fig. 2.1, Fig. 2.2).
2. Document the results of an engine oil leak detection dye test via a photo (Fig. 3).




Fig. 2.1



Fig. 2.2



Fig. 3

Subject

Oil Leak from the Engine Oil Level Sensor Area

Market

USA

Applicability

LINK REFERENCES

This Tech Tip does not contain any link references