

GPOP - Issue Review System

Part Number: 68608382A\$

Part Description: BODY CONTROL MODULE

Issue Description: After Battery Drainage BCM do not work. Please follow the following steps. 1. Check the BCM PROXI, if the BCM or any other modules are not aligned, then perform the PROXI alignment, reset the modules and perform normal ignition cycle (OFF to RUN to OFF) 2. If PROXI is correct (No misalignment), then reset the BCM module and perform normal ignition cycle. 3. Check for the DTC's and check wiring and components related to those DTC's and clear them