

9100390

07/15/2024

MY 20-23 DT 20-23 JL 21-23 DX 20-23 WK
20-23 LA 21-23 WL 20-23 LD 20-23 JT 20-
23 LX 22, 22-23 WS 20-23 WD 21-23 DS

GPOP - Issue Review System

Part Number: 68239499A\$, 68676887A\$, 68676890A\$, 68676891A\$, 68676892A\$,
68676893A\$, 68676894A\$

Part Description: D Clutch Repair Kit

Issue Description: 21-039-24 REV A - D-Clutch repair kit missing Carrier Output Shaft Seals It has been identified the Carrier Output Shaft is missing 2 seals. These seals are not available. MOPAR is working to get the parts. Do not rebuild the transmission without these seals otherwise the vehicle will not have reverse. A solution expected very soon. Transmission replacement is not recommended as this issue should be solved quickly.