



I N F I N I T I

# TECHNICAL SERVICE BULLETIN

Classification: KS21-005A	Reference: ITB22-001A	Date: May 20, 2024
------------------------------	--------------------------	-----------------------

## INTELLIGENT KEY UNIT SERVICE INFORMATION

This bulletin has been amended. See AMENDMENT HISTORY, below.  
Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2022-2024 QX60 (L51)

### SERVICE INFORMATION

- When replacing the Intelligent Key unit (hands free module), **ALWAYS** replace it with a new one.
- Module configuration **MUST BE** performed before NATS initialization (key registration). Once NATS initialization has been performed, portions of the configuration are locked and can no longer be changed.
- When replacing the Intelligent Key unit, it is critical to follow the work procedure in the ESM.
  - Refer to the ESM: **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT**

### **NOTICE**

To prevent damage to the Intelligent Key unit, perform module configuration **BEFORE** NATS initialization.

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 14, 2022	ITB22-001	Original bulletin published
May 20, 2024	ITB22-001A	<b>APPLIED VEHICLES</b> revised

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, **DO NOT** assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.