

Bulletin #: C32-0724-0654		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source:	
Date: July 23, 2024		Supersedes:	



BMW PARTS BULLETIN

TEC669 ROLLER SUNBLIND RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

54 10 7 474 476

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing incorrect "Boston" fabric. Parts containing "Reptil" fabric are ok for use.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC669 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC669 is valid from July 23, 2024, through August 06, 2024. The deadline for filing a claim under TEC669 is August 06, 2024. All parts must be returned to your facing RDC no later than August 20, 2024.

Please reorder the same part number as needed.

