

# Service Alert

Mazda North American Operations  
Irvine, CA 92618-2922



<b>Subject:</b>  PHEV COOLANT BLEEDING PROCEDURE	<b>Service Alert No.:</b> SA-004/24
	<b>Last Issued :</b> 07/11/2024

## BULLETIN NOTES

This bulletin supersedes the previously issued Service Alert(s)/Bulletin(s) listed below.

Previous SAs:	Date(s) Issued:
SA-004/24	01/19/24

## APPLICABLE MODLE(S)/VINS

2024-2025 CX-90 (PHEV)

2025 CX-70 (PHEV)

## DESCRIPTION

[Click here to view coolant bleeding procedure.](#)

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.