



## **SSM 52717 2024 Ranger - Illuminated MIL With DTCs P06DA And/Or P06DB Stored In The PCM**

Some 2024 Ranger vehicles may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P06DA and/or P06DB stored in the powertrain control module (PCM). This may be due to a damaged oil pressure control solenoid connector C1744. Before performing normal Workshop Manual (WSM) diagnostics, perform the wiggle test and inspect this connector and wires for damage. If damage is found, repair as necessary. For claiming, use causal part 14S411 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual. If no issues are found with the connector or wires, refer to WSM, Section 303-14 for normal diagnostics.