

WRB2 - Replacing Oil Note Sticker (Workshop Campaign)

Vehicle Type: **718 Cayman GT4 RS (982) / 718 Spyder RS (982)
911 GT3 RS (991) / 911 Speedster (991)
911 GT3 (992) / 911 GT3 RS (992) / 911 S/T (992)**

Model Year: **As of 2016 up to 2024**

Concerns: **Oil note sticker**

Cause: **The engine oil of the C40 specification used today for the affected vehicles is being transferred to the new Porsche C40 GT specification.**
As a result, the current data on the oil warning sticker on the vehicle must be updated.

Action: Replace the oil note sticker.

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required parts and materials

Parts Info:	Part No.	Designation	Quantity
	992010043S	⇒ Sticker	1 piece

Material: **Required materials** (usually already available in the Porsche Center):

- Cleaning agent, e.g., isopropanol*
- Cleaning cloth*

* For warranty processing, enter the part number **WRB20000001** with the designation "Consumable" as an **additional part** in the warranty claim, max. amount \$0.55.

Required tools


- Tool:
- Hot air gun

Replacing oil note sticker



Information

The oil warning sticker on all affected vehicles is located directly near the oil filler neck.



Sample illustration on the 911 GT3 RS (991)

Work Procedure: 1 Open the rear lid or service flap.

2 Locate the sticker.

NOTICE

Effects of heat from hot-air gun

- Risk of damage to paintwork, interior and peripheral components
- ⇒ Heat sticker carefully and only for as long as absolutely necessary

3 Carefully heat the affixed sticker with a hot air gun.

4 Carefully remove the sticker. Heat the sticker multiple times using the hot air gun if necessary. Remove sticker residue and clean bonding surfaces using a suitable cleaning agent (e.g., isopropanol).



Information

Make sure there are no residues from the adhesive on the old adhesive label.

After cleaning the surface, dry off the air before affixing the new adhesive label.

- 5 Destroy and dispose of the old sticker.
- 6 Affix the new sticker at the same position and with the same text alignment as the original sticker.
- 7 Close the rear lid or service flap.
- 8 Enter the campaign in the Warranty and Maintenance logbook.

Warranty processing



Information

The specified labor time was determined specifically for carrying out this campaign and includes all necessary preliminary and subsequent work. The labor time may differ from the labor time published in the Labor Operation List in the PCSS.

Scope 1:

Replace oil note sticker

Labor time:	
Replace oil note sticker	Labor time: 22 TU
Required parts:	
992010043S Sticker	1 piece
Required materials:	
WRB20000001 Consumables	1 piece
* For warranty processing, the Part No. WRB20000001 designated as "Consumable" can be invoiced as an additional part in the warranty claim. Amount \$0.55.	
⇒ Damage Number WRB2 066 000 2	

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.