

WRB7 Workshop campaign - Replacing weather sensor

WRB7 Workshop campaign - Replacing weather sensor

ID Number	WRB7
Models	Cayenne (9YA / 9YB)
Model Years	2023 - 2025
VIN List	Attached
Number of Affected VINs	877
Issue Description	<p>A weather sensor was installed on the affected vehicles which does not meet the required specifications.</p> <p>This can lead to faulty behavior of Night View Assist.</p>
What Dealers Should Do	<p>Please arrange for this action to be carried out on the affected vehicles as soon as possible, parts can be ordered immediately and the remedy is immediately available .</p>
TI	No. 23/24

Required parts

Part number	Designation	Quantity/vehicle	Parts return*
V04015800DB	Sensor for detecting humidity, rain and light	1 piece	No
9A795560920	Adhesive film for rain sensor	1 piece	No

Warranty processing

Validity:

WRB7 Workshop campaign - Replacing weather sensor

This workshop campaign will be carried out up to 02.05.2029 and will be closed by the specified date. Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Number	WRB7 66 000
Repair Code	2
Labor time	45 time units

Please enter the campaign carried out in the Warranty and Maintenance logbook for the vehicle.

Attachments

1. [WRB7 Campaign VIN Lists V2 07.26.2024.xlsx](#)