



# Preliminary Information

## PIT6166 Inside of Left Rear Door Not Completely Painted

Product Investigation Review Required

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	LYRIQ	2024	All	All	All	All
Cadillac	XT5	2024	All	All	All	All
Cadillac	XT6	2024	All	All	All	All

Involved Region or Country	North America
Condition	No or thin paint on inside of left rear door.
Cause	Manufacturing process

### Correction:

Inspect the rear lower corner of the inside of the left rear door for missing or incomplete paint.  
If the condition is found as seen in the photo below repaint the area.



### Version History

Version	<b>1</b>
Modified	05/06/2024 - Created on.



GENERAL MOTORS

© 2024 General Motors. All Rights Reserved.