



Bulletin No.: PIT6176
Published date: 05/15/2024


Preliminary Information

PIT6176 Front License Plate Screws Included in Kit Do Not Fit License Plate Bracket

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Envision	2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	VK3 - FRONT LICENSE PLATE BRACKET
Condition	Some technicians may find during pre-delivery inspection that the front license plate fasteners (highlighted in red below) that attach the license plate included in the front license plate kit, do not fit with the push nuts attached to the bracket.
Cause	The incorrect fasteners were included with the front license plate bracket.



Correction:

Replace the M5 fasteners with M6 fasteners.

Parts Information

Description	Part Number	Quantity
M6 Fastener	11546571	4

Version History

Version	1
Modified	05/15/2024 - Created on



© 2024 General Motors. All Rights Reserved.