



**Bulletin No.:** PIT6181  
**Published date:** 06/3/2024

## Preliminary Information

**PIT6181 Diagnostic Aid: Lane Keep Assist and Forward Collision Alert Indicators On While Driving. No DTCs Stored.**

### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b>	<b>Engine:</b>	<b>Transmissions:</b>
			<b>from to</b>		
Chevrolet	Equinox	2018 - 2024	All	All LYX	All
GMC	Terrain	2018 - 2024	All	All LYX	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Additional RPO/s:</b>	<b>UEU, UHX</b>
<b>Condition:</b>	<b>Lane Keep Assist and Forward Collision Alert indicators turn on and off while driving.</b>
<b>Cause:</b>	<b>Incorrect or mismatched tires installed on the vehicle.</b>



If you duplicate this concern and there are no DTCs stored inspect the tires and match to the door tag and verify all 4 tires are the same brand, size and wear. The difference in wheel speed inputs will cause the systems to disable.

### Version History

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>06/03/2024 - Created on.</b>



GM Global Brands  
 © 2024 General Motors. All Rights Reserved.