



**Bulletin No.:** PIC6558

**Published date:** 06/13/2024

## Preliminary Information

### PIC6558 360 Camera Image Distorted

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN:</b>	<b>Engine:</b>	<b>Transmissions:</b>
Cadillac	CT5	2025	from to	All All All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Condition</b>	<b>A customer may comment that the image displayed from the 360 degree cameras are distorted.</b>
<b>Cause</b>	<b>This concern is a result of a software anomaly.</b>


#### Correction:


Engineering is developing a software solution.

**Do not attempt any repairs for this concern.**

**This PI will be converted to a Technical Service Bulletin when a solution is available.**

**See images below for a example of this concern:**





**Version History**

<b>Version</b>	<b>1</b>
<b>Modified</b>	<b>06/13/2024 - Created on.</b>