



Bulletin No.: PIT6168A

Published date: N/A

Preliminary Information

PIT6168A DTC U3000 SYM57 Setting After Replacing Left Or Right Side Object Detection Control Module

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Corvette	2022 - 2023	All All	All	All
Buick	Envision	2021 - 2023	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UFG / UFT / UKC - Side Object Detection
Condition	A technician may find DTC U3000 SYM57 setting in the Left or Right Side Object Detection Control Module after replacing and programming has been completed.
Cause	The cause of the condition is a software anomaly that Engineering is aware of.

Correction:

Contact TAC for further direction.

Version History

Version	1
Modified	05/07/2024 - Created on. 06/18/2024 - Updated Model List

 GM Global Brands

© 2024 General Motors. All Rights Reserved.