

Bulletin #: C32-0824-0660		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title: Material Flow & Inventory Integrity		Source: Parts Logistics	
Date: August 26, 2024		Supersedes:	



BMW PARTS BULLETIN

TEC676 WINDSHIELD COVER RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

51 31 5 B33 6B2

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far containing incorrect part in package.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC676 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC676 is valid from August 26, 2024, through September 09, 2024. The deadline for filing a claim under TEC676 is September 09, 2024. All parts must be returned to your facing RDC no later than September 23, 2024.

Please order the same part number as needed.

