

To re-establish your vehicles true 100% state of charge please:

- Charge your vehicle +10% from current SOC
- Update to .27 SW
- Charge your vehicle to 100% SOC to recalibrate maximum charge.