

Field campaign

Topic	Passenger door control unit replacement (SC24/18)
Market area	Australia E04 Bentley rest Asia and Australia (6E04),Germany E02 Bentley rest Europe (6E02),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2074678/1
Campaign number	ED11
Note	
Type	
US code	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
ZV14D9	2024	E	SUV KoVOMo BY636 404/V8 8AG	DWRA	VNV	QUT

Documents

Document name
master.xml
sc2418vinilst.pdf

Notes

[Repair instructions](#)

Technical background

Customer experiences 12V battery completely flat. This is caused due to headlight fans which are turning on after the car has been locked. Chip Mismatch during production of PCB's of passenger door CU is keeping the BUS awake and headlight fans being on and draining 12V battery.

Remedy

Replace the front passenger door control unit. Refer to 'Front door control unit – To remove and fit'

Customer notification

Customers do not need to be informed directly of this campaign. Please ensure all affected vehicles are checked and repaired at the nearest opportunity.

Warranty accounting instructions

Warranty type 710 or 790

Damage service number ED11

Damage code 00 66

Criteria 01

Time to replace the front door control unit

Labour Operation Code 64 38 19 00

Time 30 TU

Time to code front door control unit

Labour Operation Code 01 51 00 00

Time As per the ODIS log (Must not exceed 50 TU)

Genuine parts

4M1959952K

Parts supply

The required part should be ordered through your regional Bentley parts distribution centre

Parts despatch control

Not applicable

Repair instructions

[Notes](#)

Technical background

Customer experiences 12V battery completely flat. This is caused due to headlight fans which are turning on after the car has been locked. Chip Mismatch during production of PCB's of passenger door CU is keeping the BUS awake and headlight fans being on and draining 12V battery.

Check

If the vehicle is not already listed as repaired in the 'Repair history' section of Elsapro, check for presence of the yellow paint mark as detailed within the identification section.

In the event the campaign has not been applied, please carry out the required work in accordance with these instructions.

Genuine parts

4M1959952K

Work

CAUTION

CAUTION: The Bentley ODIS-S Brand version **MUST** be 2.32.0 or higher

Referring to Elsapro, replace the front door control unit.

Identification

Yellow paint mark on the passengers seat outer rail (behind fixing) confirms completion

 [Repair instructions](#)  [Notes](#)

SJAHT2ZV8RC025083
SJAHB14V8RC025086
SJAHT2ZV7RC025088
SJAHT2ZV5RC025090
SJAHT2ZV2RC025094
SJAHB14V0RC025096
SJAHA14V5SC025099
SJAHA14V8SC025100
SJAHA14V1SC025102
SJAHA14V3SC025103
SJAH814V0SC025104
SJAH814V2SC025105
SJAHB14V2SC025106
SJAH814V8SC025108
SJAH72ZV8SC025109
SJAHA14V0SC025110
SJAH814V9SC025117
SJAHT2ZV9RC025125
SJAHP14V7RC025128
SJAHT2ZV2RC025130
SJAHP14V2RC025134
SJAHT2ZV3RC025136
SJAHT2ZV5RC025137
SJAHT2ZV9RC025139
SJAHT2ZV9RC025142
SJAHB14V7RC025144
SJAHP14V9RC025146
SJAHT2ZVXRC025151
SJAHT2ZV1RC025152
SJAHP14V8RC025154
SJAHT2ZV9RC025156
SJAHT2ZV2RC025161
SJAHT2ZV8RC025164
SJAHB14V6RC025166
SJAHT2ZV5RC025168
SJAHT2ZV3RC025170
SJAHB14V5RC025174
SJAHP14V9RC025177
SJAHP14V2RC025179
SJAHP14V4RC025183
SJAHT2ZV0RC025188
SJAHP14V3RC025191
SJAHP14V9RC025194
SJAHB14V8RC025198
SJAHP14V0RC025200
SJAHB14V8RC025203
SJAHB14V3RC025206
SJAHT2ZV4RC025209
SJAHT2ZV0RC025210
SJAHT2ZV6RC025213

SJAHT2ZVXRC025215
SJAHT2ZV3RC025217
SJAHT2ZV7RC025219
SJAHB14V8RC025220
SJAHB14V3RC025223
SJAHP14V9RC025227
SJAHP14V9RC025230
SJAHT2ZV8RC025231
SJAHP14V6RC025234
SJAHP14V1RC025240
SJAHB14V6RC025247
SJAHP14V8RC025249
SJAHT2ZV7RC025253
SJAHB14V5RC025255
SJAHT2ZV6RC025258
SJAHB14V4RC025263
SJAHT2ZV3RC025265
SJAHB14V1RC025267
SJAHT2ZV7RC025270
SJAHB14V4RC025277
SJAHT2ZVXRC025280
SJAHB14VXRC025283
SJAHB14V7RC025290
SJAHB14V8RC025301
SJAHB14V3RC025304
SJAHB14V9RC025307
SJAHB14V9RC025310
SJAHB14V6RC025314
SJAHB14V5RC025319
SJAHT2ZV6RC025325
SJAHT2ZV1RC025328
SJAHT2ZV3RC025329
SJAHB14V6RC025331
SJAHB14V5RC025336
SJAHP14V5RC025340
SJAHP14V0RC025343
SJAHB14V8RC025346
SJAHU1ZV3RC025452
SJAHB14V2RC025455
SJAHB14V8RC025458
SJAHB14V8RC025461
SJAHP14V7RC025467
SJAHB14V0RC025468
SJAHP14V7RC025470
SJAHT2ZV6RC025471
SJAHB14V4RC025473
SJAHT2ZV5RC025476
SJAHP14V3RC025479
SJAHU1ZV5RC025503
SJAHP14V8RC025509

SJAHB14V6RC025510
SJAHB14VXRC025512
SJAHP14V7RC025517
SJAHP14V9RC025518
SJAHU1ZV7RC025521
SJAHT2ZV7RC025527
SJAHP14V0RC025536
SJAHT2ZV1RC025538
SJAHP14V9RC025549
SJAHB14V0RC025552
SJAHT2ZV1RC025555
SJAHB14VXRC025557
SJAHU1ZV6RC025560
SJAHB14V3RC025562
SJAHP14V3RC025658
SJAHT2ZV2RC025662
SJAHT2ZV8RC025665
SJAHB14V8RC025668
SJAHP14V4RC025670
SJAHB14V8RC025671
SJAHP14VXRC025673
SJAHT2ZV4RC025677
SJAHP14V0RC025679
SJAHT2ZV4RC025680
SJAHP14V0RC025682
SJAHP14V6RC025685
SJAHB14V5RC025689
SJAHP14V1RC025691
SJAHP14V7RC025694
SJAHT2ZVXRC025697
SJAHP14V9RC025700
SJAHB14V4RC025702
SJAHP14V6RC025704
SJAHT2ZVXRC025716
SJAHB14V6RC025720
SJAHB14V1RC025723
SJAHB14V3RC025724
SJAHP14V9RC025728
SJAHP14V7RC025730
SJAHP14V0RC025732
SJAHT2ZV1RC025734
SJAHP14V3RC025739
SJAHP14V1RC025741
SJAHP14V9RC025745
SJAHP14V2RC025747
SJAHP14V6RC025749
SJAHP14V3RC025756
SJAHT2ZV6RC025759
SJAHP14V0RC025763
SJAHP14V6RC025766

SJAHP14V1RC025769
SJAHT2ZV7RC025771
SJAHB14V5RC025773
SJAHP14V7RC025775
SJAHP14V2RC025778
SJAHT2ZVXRC025781
SJAHU1ZV6RC025784
SJAHP14V1RC025786
SJAHP14V5RC025788
SJAHP14V3RC025790
SJAHB14V9RC025792
SJAHT2ZV8RC025794
SJAHP14V4RC025796
SJAHT2ZV5RC025798
SJAHP14V8RC025803
SJAHB14V3RC025805
SJAHP14V7RC025808
SJAHT2ZV2RC025810
SJAHB14V0RC025812
SJAHT2ZVXRC025814
SJAHU1ZV4RC025816
SJAHP14VXRC025818
SJAHU1ZV6RC025820
SJAHP14V3RC025823
SJAHP14V0RC025827
SJAHP14V0RC025830
SJAHP14V6RC025833
SJAHP14V8RC025834
SJAHT2ZV0RC025837
SJAHT2ZV4RC025842
SJAHP14V0RC025844
SJAHP14V6RC025850
SJAHT2ZV7RC025852
SJAHU1ZV1RC025854
SJAHB14V0RC025857
SJAHP14V2RC025859
SJAHU1ZV7RC025860
SJAHU1ZV6RC025865
SJAHP14VXRC025866
SJAHU1ZV3RC025869
SJAHP14V5RC025872
SJAHP14V9RC025874
SJAHU1ZV0RC025876
SJAHT2ZV5RC025879
SJAHP14V6RC025881
SJAHP14V1RC025884
SJAHP14V9RC025888
SJAHP14V7RC025890
SJAHP14V0RC025892
SJAHP14V6RC025895

SJAHB14V1RC025897
SJAHP14V3RC025899
SJAHT2ZV7RC025902
SJAHT2ZV0RC025904
SJAHP14V5RC025905
SJAHP14V9RC025910
SJAHP14V0RC025911
SJAHB14V6RC025913
SJAHT2ZV3RC025914
SJAHP14VXRC025916
SJAHP14V5RC025919
SJAHT2ZV2RC025922
SJAHB14V0RC025924
SJAHP14V2RC025926
SJAHB14V8RC025931
SJAHP14V5RC025936
SJAHP14V9RC025938
SJAHP14V0RC025939
SJAHT2ZV8RC025942
SJAHP14V6RC025945
SJAHP14VXRC025947
SJAHP14V1RC025951
SJAHP14V5RC025953
SJAHU1ZV7RC025955
SJAHP14V4RC025958
SJAHT2ZV1RC025961
SJAHP14VXRC025964
SJAHP14V1RC025965
SJAHP14V7RC025971
SJAHP14V0RC025973
SJAHP14V4RC025975
SJAHP14VXRC025978
SJAHP14VXRC025981
SJAHT2ZV0RC025983
SJAHP14V7RC025985
SJAHP14V4RC025989
SJAHP14V8RC025994
SJAHT2ZV0RC025997
SJAHT2ZV4RC026005
SJAHP14V9RC026006
SJAHP14V0RC026010
SJAHP14V4RC026012
SJAHP14VXRC026015
SJAHP14V5RC026018
SJAHP14V3RC026020
SJAHT2ZV4RC026022
SJAHP14V4RC026026
SJAHP14V8RC026028
SJAHP14V1RC026033
SJAHP14V5RC026035

SJAHB14V2RC026038
SJAHP14V2RC026039
SJAHP14V6RC026044
SJAHT2ZV9RC026047
SJAHT2ZV2RC026049
SJAHP14V3RC026051
SJAHT2ZV4RC026053
SJAHP14V9RC026054
SJAHT2ZVXRC026056
SJAHP14V6RC026058
SJAHP14V5RC026066
SJAHP14V9RC026068
SJAHP14V7RC026070
SJAHP14V4RC026074
SJAHU1ZV4RC026075
SJAHP14VXRC026077
SJAHP14V3RC026082
SJAHT2ZV2RC026083
SJAHU1ZV7RC026085
SJAHU1ZV2RC026091
SJAHP14VXRC026094
SJAHP14V3RC026096
SJAHT2ZV6RC026099
SJAHT2ZV0RC026101
SJAHT2ZV8RC026105
SJAHP14V4RC026107
SJAHT2ZV5RC026109
SJAHU1ZV4RC026111
SJAHP14V3RC026115
SJAHT2ZV6RC026118
SJAHP14V7RC026120
SJAHT2ZV6RC026121
SJAHT2ZVXRC026123
SJAHP14V6RC026125
SJAHP14V8RC026126
SJAHT2ZV9RC026128
SJAHP14V3RC026132
SJAHP14V5RC026133
SJAHU1ZV7RC026135
SJAHB14V3RC026243
SJAHP14V5RC026245
SJAHB14V0RC026247
SJAHB14V4RC026249
SJAHP14V4RC026253
SJAHS14V5RC026261
SJAHT2ZV7RC026273
SJAHP14V9RC026281
SJAHU1ZV4RC026285
SJAHP14VXRC026287
SJAHP14V3RC026289

SJAHU1ZV1RC026292
SJAHP14V7RC026294
SJAHS14V2RC026296
SJAHB14V6RC026303
SJAHP14V5RC026309
SJAHT2ZV4RC026313
SJAHB14VXRC026319
SJAHT2ZV0RC026521