



Bulletin No.: PIT6048A
Published date: 07/16/2024

Preliminary Information

PIT6048A Transmission Temperature Gauge Shows Hot

Proactive


Models


Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Cadillac	XT4	2024	All All	All	All
Chevrolet	Colorado	2023	All All	All	All
GMC	Canyon	2023	All All	All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD
Condition	Customers may comment that their transmission temperature gauge shows hot.
Cause	This could be caused by a software anomaly.

Correction:

Confirm that the customer is describing the concern of the transmission temperature gauge showing high and red, like in the 2 pictures below.





Verify the transmission temperature does not go above 123C (269.6F).

***Note: For XT4, USB Update the A11 Radio in SPS2.**

For Canyon/Colorado, advise the customer that engineering is aware of the issue and the correction will be released in a later radio software update.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*3487918	Verify Transmission Temperature Gauges Reads Hot	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	2
Modified	08/09/2023 - Created On. 7/16/2024 - add Note for XT4 Correction