



Bulletin No.: PIT6029A
Published date: 07/16/2024

Preliminary Information

PIT6029A Diagnostic Aid: DTC B17E2 Stored Current In The MSM

Models

Brand:	Model:	Model Years:	VIN: from	Engine:	Transmissions: to
Chevrolet	Colorado	2023 - 2024	All	All	All
GMC	Canyon	2023 - 2024	All	All	All

Involved Region or Country:	North America
RPO	A45
Condition:	Code B17E2 stored current in the MSM. The vehicle may come in with it or be present after MSM programming.
Cause:	Module software.

Condition:

The 2023 Colorado and Canyon do not use a headrest position sensor and the module is setting a false code due to the current software.

This will be fixed in a future software release and does not cause any issues if present.

Diagnose any other codes or symptoms if there is a seat issue.

Version History

Version	2
Modified	06/08/2023 - Created. 07/16/2024 - Added 2024 Model Year.