



Bulletin No.: PIT6073C
Published date: 07/19/2024

Preliminary Information

PIT6073C Front Heated Seat Switch Indicator Lights Inoperative When Heated Seats Are Turned On And Operate

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Silverado	All 2023 - 2024	All	All All	All
GMC	Sierra	All 2023 - 2024	All	All All	All

Involved Region or Country	North America, Australia (GMSV)
Additional Options (RPO)	CJ2- Auto HVAC
Condition	Some customers may comment that when the front heated seats are turned on, the heated seats work normally, but some or all of the "ON" indicators in the heated seat switch are inoperative. Because a heated seat switch indicator is inoperative, a customer may also think that the front heated seats are inoperative, but the heated seats will still operate.
Cause	The cause of this concern, could be an issue with the A26 Front HVAC Control Interface.

Correction:

To correct this codition, replace the A26 Front HVAC Control Interface.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4420100	Heater and Air Conditioning User Interface Control Replacement	Use Published Time

Version History.

Version	4
Modified	10/11/2023 - Created on 10/16/2023 - Updates to the model list, condition and correction sections. 04/26/2024 - Update to the admin notes 07/19/2024 - Update to the correction and warranty sections.