

Reference	SSM76140
Models	New Range Rover / L460
Title	SV Signature Suite – Rear Floor Console Deployable Table Not Stowing
Category	Body
Last modified	06-Aug-2024 00:00:00
Symptom	107000 Interior Trim

Content **Model / Model Year / Derivative**

Range Rover / 23MY Onwards / with SV Signature Suite (Rear Console Deployable Table)

Situation:

JLR Engineering investigations have found reports of the rear floor console deployable table is not stowing correctly on vehicles equipped with 'SV Signature Suite'.

When the SV Signature Suite is in the raised position, a user may find they are unable to lower it by pressing the 'lower' button on the touch screen. The button will not be highlighted as it should be.

Note: Make sure the table leaves are closed and the table is pushed fully forward on its slides (the correct position for lowering). Refer to: iGuide > Convenience Features > Rear Centre Console Table, for operation instructions.

Action:

Follow the instruction(s) below:

SERVICE INFORMATION:

Do not complete any further diagnostics or disassembly of the Signature Suite Console, this includes programming of modules.

1. Select 'Fault and Breakdown'
2. Select one of the following SYMPTOMS
 - 'Body > Trim and Ornamentation > Rear Floor Console Table > Not Stowing'
 - 'Body > Trim and Ornamentation > Rear Floor Console Table > Inoperative'
 - 'Body > Trim and Ornamentation > Rear Floor Console Table > Does Not Operate As Expected'
3. Run the Recommended Action 'Rear Floor Console Table Not Stowing – Test'
4. Follow the on-screen instructions.

(Ref 000370478)