

ACM Fault 3711/31 – DOC In Temp Low 2023 MDEG Engine Builds



Description

- Spike in fault 3711/31 observed on CY23-built MDEG units with ACM software 13.58.2.0.
 - Fault likely to be intermittent as it is driven by small torque spikes.
 - Fault will set a MIL – does not have a regen inhibit or have a derate.

Factory Resolution

- PCA is already in 2024 Production Software 13.58.4.0.

Field Resolution

- Regulatory submission submitted on July 24th–service testing can begin August 26th.
- Free release date TBD in late August/early September after initial service test completes.
- Troubleshooting will be updated to include software check once available.