



2024-08-07



M1654: DTII MODULE REPLACE MENU CHANGE

Reason for Revision

Table 1

Table 1. Document History

Date	Rev	Revision (Rev) Description
2024-08-07	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealer technicians that there is a new menu item in Digital Technician II (DT II). DT II now has a stand alone Module Replace menu inside of Vehicle Setup. This will allow you to program the factory settings, for the connected vehicle, to the Electronic Control Module (ECM), Body Control Module (BCM) and Infotainment Control Unit (IFCU) (if equipped) in a single menu.

- 2021 and later Revolution Max: ECM, BCM, Speedometer (SPDO)
- 2023 and later CVO Touring: ECM, BCM, IFCU
- 2024 Street Glide (FLHX), Road Glide (FLTRX): ECM, BCM, IECU

Required Dealer Action

Table 2. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☐
2	Repair If Presenting Symptom	☐
3	Feature Pack-Customer/Dealer Paid	☐
4	Informational Purposes Only	☒

NOTE

The module replace process should be done anytime one of the selectable modules has been replaced on the vehicle or if it is desired to return the existing module back to its factory settings.

1. Established connection between DT II and the vehicle.
2. **Select:** TOOLBOX Icon.
3. **Select:** VEHICLE SETUP

4. **Select:** MODULE REPLACE. See Figure 1.
 - a. See Figure 2. In this menu you will be able to select from ECM, BCM or IFCU.
5. See Figure 3. Confirm selected module software is the latest, this check is automatically done.
 - a. You will need to select Cancel, Reflash or Proceed.
6. See Figure 4 and Figure 5. Once the process is complete, DT II will show what next steps are required, if any are needed for the selected module.

NOTE

IFCU software is not done through DT II. Software level needs to be confirmed by checking the Infotainment Support Resources page on the Service Information Portal (SIP).

Electronic Isheet Links:

- *Refer to: Infotainment Support Resources*
- *Refer to: <https://serviceinfo.harley-davidson.com>*

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]




Figure 1. Module Replace




Figure 2. Select Replacement Module




Figure 3. Module Selection with Software Version




Figure 4. Update in Process




Figure 5. Process Complete