



Bulletin No.: PIT6208


Published date: 07/24/2024

Preliminary Information

PIT6208 UOTA Notification Showing Up In Vehicle IHU Screen

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Chevrolet	Colorado	2024	All	All All	All
GMC	Canyon	2024	All	All All	All

Involved Region or Country	North America
Additional Options (RPO)	IVD
Condition	<p>Customers may experience an Infotainment notification with "GAS_aap-client, UOTA App is running". This is an indication that minor software update is occurring in the background to improve the vehicle. This will not be a full over-the-air system software update, so it will not require the vehicle to be in park. Update time is relatively short in nature. The customer can dismiss the notification.</p> 
Cause	The cause is a software update occurring in background

Correction:


Please do not replace any parts at this time.

Engineering is aware of this message.

This is an indication that minor software update is occurring in the background to improve the vehicle. This will not be a full over-the-air system software update, so it will not require the vehicle to be in park. Update time is relatively short in nature. The customer can dismiss the notification.

Version History

Version	1
Modified	07/24/2024 - Created On.

 GM Global Brands
© 2024 General Motors. All Rights Reserved.