



Bulletin No.: PIP5986A

Published date: N/A

Preliminary Information

PIP5986A Diagnostic Tip:DTC P219A Set As Current Or History But Easily Duplicated

Proactive

Models

Brand: Model: Model Years: VIN: Engine: Transmissions:
from to

Chevrolet Traverse 2024 All All 2.5 LK0 All

GMC Acadia 2024 All All 2.5 LK0 All

Involved Region or Country:	North America
Condition:	DTC P219A set as current or history
Cause:	GM Engineering is aware of the condition and validating a repair

Correction

If you encounter DTC P219A that is set as current or easily duplicated please clear the DTC and advise the customer GM Engineering is aware of the issue and currently working toward a permanent repair for this condition.

This PI will be upgraded to a bulletin once all the repair information becomes available.

Version History

Version	2
Modified	06/12/2024 - Created on. 07/26/2024- Updated to remove diagnostic steps and labor time.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.