



An Oshkosh Corporation Company

GENERAL BULLETIN GB2024004 IMT COMPRESSOR MOTOR CHANGE

Subject:	IMT Compressor Motor Change
Attn:	IMT Distributors
From:	IMT Tech Support
Date:	August 08, 2024
Affected Models:	CAS40PL & CAS40PL-CW

Why are you receiving this bulletin?

IMT has identified that hydraulic back pressure can lead to leaks in the **CAS40PL or CAS40PL-CW** motor in certain system setups. As a solution, IMT is shifting to a motor design that includes an internal check valve to reduce the likelihood of failure from back pressure. All units produced after **June 15, 2024**, bearing the serial number **30-24068707 or later**, will be equipped with this updated motor. This new motor is designed to be a direct replacement, ensuring full backward compatibility with the existing system configuration.

What should you do?

If you experience a motor leak on your **CAS40PL & CAS40PLCW**, order the new replacement motor with part number **73511499**. IMT will reimburse for the motor and up to one hour of labor to repair the unit. Follow the standard IMT warranty process to file the claim and receive credit.

Do you have questions?

If you have any questions or need additional assistance, please contact IMT Technical Support at 1-800-554-4421 or 641-923-4633.