



Bulletin No.: PIT6176A
Published date: 07/30/2024

Preliminary Information

PIT6176A Front License Plate Screws Included in Kit Do Not Fit License Plate Bracket

Models

Brand: Buick **Model:** Envision 2024 **Model Years:** All **VIN:** All All **Engine:** All All **Transmissions:** All

Involved Region or Country	North America
Additional Options (RPO)	VK3 - FRONT LICENSE PLATE BRACKET
Condition	Some technicians may find during pre-delivery inspection that the front license plate fasteners (highlighted in red below) that attach the license plate included in the front license plate kit, do not fit with the push nuts attached to the bracket.
Cause	The incorrect fasteners were included with the front license plate bracket.



Correction:

Replace the M5 fasteners with M6 fasteners.

Parts Information

Description	Part Number	Quantity
M6 Fastener	11546571	4

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
1086848	Replace incorrect M5 fasteners with M6 fasteners	0.1 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	1
Modified	05/15/2024 - Created on. 07/30/2024 - Updated Labor Operation.