

REFERENCE:	TSB: 21-035-24 REV. A GROUP: 21 - Transmission and Transfer Case	Date:	September 5, 2024	REVISION:	21-035-24
VEHICLES AFFECTED:	2024 (GC) Alfa Romeo Tonale This bulletin applies to vehicles built on or before March 25, 2024 (MDH 0325XX) equipped with a 2.0L I4 DOHC DI Turbo Engine w/ESS (Sales Code EC1) and 9-Speed 948TE FWD/AWD Auto Trans (Sales Code DFH) .			MARKET APPLICABILITY:	
				<input checked="" type="checkbox"/> NA	<input type="checkbox"/> MEA
				<input type="checkbox"/> SA	<input type="checkbox"/> IAP
				<input type="checkbox"/> EE	<input type="checkbox"/> CH
CUSTOMER SYMPTOM:	Customers may experience: <ul style="list-style-type: none"> Shift paddles will not work when the shifter is in Drive. Shift paddles only work when the transmission is in manual mode. 				
CAUSE:	TCM software				

This bulletin supersedes Technical Service Bulletin (TSB) 21-035-24, date of issue May 21, 2024, which should be removed from your files. All revisions are highlighted with **asterisks**** and include a Note and converting the TSB to an Information Only bulletin.**

DISCUSSION:

NOTE: **This service action is no longer in effect. Please follow published service procedures in Service Library to diagnose and repair the vehicle.******

POLICY:

****Information Only.****

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.