



**Bulletin No.:** PIT6217

**Published date:** 08/20/2024

## Preliminary Information

### PIT6217 Gray Task Bar On Radio Display

#### Proactive

#### Models

<b>Brand:</b>	<b>Model:</b>	<b>Model Years:</b>	<b>VIN: from to</b>	<b>Engine:</b>	<b>Transmissions:</b>
Buick	Enclave (All New)	2025	All	All	All
Cadillac	LYRIQ	2023 - 2024	All	All	All
Cadillac	XT4	2024 - 2025	All	All	All
Chevrolet	Blazer EV	2024	All	All	All
Chevrolet	Colorado	2023 - 2024	All	All	All
Chevrolet	Equinox	2025	All	All	All
Chevrolet	Equinox EV	2024	All	All	All
Chevrolet	Silverado EV	2024	All	All	All
Chevrolet	Traverse (All New)	2024	All	All	All
GMC	Acadia (All New)	2024	All	All	All
GMC	Canyon	2023 - 2024	All	All	All
GMC	Sierra EV	2024	All	All	All

<b>Involved Region or Country</b>	<b>United States, Canada, Mexico</b>
<b>Additional Options (RPO)</b>	<b>IVD and IVE</b>
<b>Condition</b>	<b>Some customers may comment that the task bar on the radio display is now gray when it was previously black.</b>
<b>Cause</b>	<b>This is due to a software anomaly.</b>

#### Correction:

**GM is aware of this issue and will provide an update through a service bulletin when a fix becomes available.**

**Please do not replace any parts at this time.**

#### Warranty Information


**For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.**

<b>Labor Operation</b>	<b>Description</b>	<b>Labor Time</b>

Labor Operation	Description	Labor Time
3486198	Verify gray task bar on radio display	0.2 Hr.
*This is a unique Labor Operation for Bulletin use only.		

### Version History

Version	1
Modified	08/20/2024 - Created On.

 GM Global Brands  
© 2024 General Motors. All Rights Reserved.