



Bulletin No.: PIT6221

Published date: 08/20/2024

Preliminary Information

PIT6221 Steering Wheel Oscillates or Vibrates in Super Cruise Mode

Models

Brand:	Model:	Model Years:	VIN: from to	Engine:	Transmissions:
Buick	Enclave	2025	All	All	All
Chevrolet	Traverse (all new)	2024	All	All	LK0
Chevrolet	Traverse	2025	All	All	All
GMC	Acadia	2024 - 2025	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UKL
Condition	Steering wheel vibrating, dithering, or oscillating while driving. This condition will only be experienced when driving with super cruise activated. If this condition is experienced with super cruise turned off this PI does not apply.
Cause	Software

Correction:

Do not perform any repairs at this time.

Engineering is working on updated software which will be available by mid- September.

When software for this concern becomes available a bulletin will be released.

Warranty Information

Version History

Version	1
Modified	08/20/2024 - Created on.