



SSM 52967 Various Ford And Lincoln Vehicles - Passive Key Will Not Program

Some of the following vehicles may exhibit a condition where the passive key will not program to the vehicles:

- * 2024 F-150 non-Lightning
- * 2023-2024 F-Super Duty
- * 2025 Explore/Aviator
- * 2024 Nautilus
- * 2024 Mustang vehicles built on or after 31-May-2024
- * 2024 Bronco vehicles built on or after 01-June-2024

If a key does not program, rotate the key 180 degrees in the passive key backup starting location versus what is recommended in the Owners Manual Section > "Starting and Stopping the Engine - Accessing the Passive Key Backup Position" and then reattempt programing. If the key still does not program, refer to Workshop Manual (WSM), Section 419-01 for normal diagnostics.