

Bulletin #: C32-0924-0669		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: September 17, 2024		Supersedes:	



# BMW PARTS BULLETIN

## TEC686 WINDOW BORDER COVER RETURN

### TAKE ACTION

BMW AG has requested the return of the following part numbers:

51 33 9 891 447                      51 33 9 891 448

**Affected available inventory must not be sold.**

**Concerned are all parts delivered and shipped so far missing the foam insert shown in image below. Parts containing the foam insert are ok for use.**

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC686 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

**TEC686 is valid from September 17, 2024, through October 01, 2024. The deadline for filing a claim under TEC686 is October 01, 2024. All parts must be returned to your facing RDC no later than October 15, 2024.**

Please reorder the same part number if needed.

