

Bulletin #: C32-0924-0671		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: September 19, 2024		Supersedes:	



BMW PARTS BULLETIN

TEC688 THERMOSTAT RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

11 53 1 436 386

Affected available inventory must not be sold.

Concerned are all parts delivered and shipped so far missing sensor. Parts containing sensor are ok for use.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC688 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC688 is valid from September 19, 2024, through October 03, 2024. The deadline for filing a claim under TEC688 is October 03, 2024. All parts must be returned to your facing RDC no later than October 17, 2024.

Please reorder the same part number if needed.

