

9PA PCCM+ Installation Causes Malfunction Indicator Light

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne S/ GTS	2008	9PAAH, 9PAAL	n/a	n/a

Revision History

Revision	Release Date	Changes
0	May 12, 2023	Original document
1	May 25, 2023	Update of Warranty Information
2	September 19, 2024	Update of order types and software version

Condition

After completing installation of the Porsche Classic Communication Management Plus (PCCM+) in the above-mentioned vehicle, the customer may have a concern of an illuminated Malfunction Indicator Light accompanied by one or more of these faults:

- DME
P1530 - Time information via CAN missing (Signal implausible)
- Instrument cluster
1299 - GATEWAY (No signal/communication)
0459 - PCM2 (No signal/communication)
- Gateway
0459 - PCM2 (No signal/communication)

Service Information

If the above-mentioned condition is confirmed, update the PCCM+ according to the instructions located in the *PCM – NAV – Map info & Navigation Updates* PPN space under Special Tools and Equipment:
<https://ppn.porsche.com/portal/docs/DOC-462444>

The relevant information is located under "PCCM (Porsche Classic Communication Management) Plus 9PA/E1"

Precondition:

Verify vehicle is a 2008 Cayenne S/ GTS with a PCCM+ installed with check engine light illuminated.

Step 1 (12 TU):

Check version of PCCM+ to verify software version:

- CAN-20240715 - perform scope 2 (Attach required photo to PCSS job: PCCM+ with version displayed)
- **Not** CAN-20240715 – do not perform scope 2 (Attach required photos to PCSS job: VIN, MIL, PCCM+ with version displayed)

Step 2 (100 TU):

Scan vehicle and send VAL

Verify codes present

DME

- P1530 - Time information via CAN missing(Signal implausible)

Instrument cluster

- 1299 - GATEWAY (No signal/communication)
- 0459 - PCM2 (No signal/communication)

Gateway

- 0459 - PCM2 (No signal/communication)

Update PCCM plus to CAN Version: CAN-20240715

Disconnect and reconnect battery

Clear faults

Send updated VAL

Warranty

Warranty type code:	121	
Step 1:	91109590	12TU
Step 2:	03350050	10TU
	03350056	25TU
	91129590	65TU

Search Items

PCCM+, CEL, MIL, Check Engine Light, P1530

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.