

WRP8 Workshop Campaign - Checking sliding roof and replacing control unit for sliding roof if necessary

Update 9/17/24

Please be advised that the "check" can now be completed on vehicles affected by WRP8. If a vehicle fails the check, please submit a PPL order with PRMS Parts Support ticket for release of the control unit.

IMPORTANT: If the vehicle's sunroof fails the check, the customer is not obligated to take delivery of the vehicle. We have crafted the attached Pre-Sale Disclosure form, which the customer should sign in the event that they still want to take delivery of a vehicle with a non-functional sunroof and return for the campaign repair when parts are available.

The TI is now available in PCSS and the [AfterSales Document Database](#).

WRP8 Workshop Campaign - Checking sliding roof and replacing control unit for sliding roof if necessary

| | |
|-----------------------------|---|
| ID Number | WRP8 |
| Models | Macan (XAB) |
| Model Years | 2024 |
| VIN List | Attached below |
| Number of affected vehicles | 67 |
| Issue Description | <p>It is possible that a transistor that does not meet the specifications has been installed in the sunroof control unit of the affected vehicles.</p> <p>If this is the case, a malfunction will occur, and it will no longer be possible to operate the sunroof.</p> <p>Therefore, the function of the sunroof must be checked before the vehicles are delivered to the customers, replacing the sunroof control unit if necessary.</p> |

In the event that the sunroof control unit needs to be replaced, even if availability of the required parts is delayed, a customer can still receive the vehicle with temporarily restricted functional scope on request. Customer information, which must be countersigned accordingly by the customer, is provided for this purpose.

Once the required spare part is available, the repair can be carried out to bring about full functionality of the vehicle.

What should Porsche Centers do?

Please arrange for this action to be taken on the affected vehicles before the vehicles are handed over to customers.

The remedy is now available as of 9/17/24.

TI

[No. 155-24](#)

Attachments

- [1. VIN_List_Report_WRP8_2024-09-10_V2.xlsx](#)
- [2. WRP8 Macan Sunroof Pre-Sale Disclosure_Final.pdf](#)