



## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.**

**TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas, Atlas Cross Sport	2024-2025	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2075443/1	9/26/ 2024	97-24-01TT	Original publication.

## Technical Background

In MY2024-25 Atlas, Atlas Cross Sport the Immobilizer identity is stored within the Vehicle Electrical System Control Module -**J519**. If all vehicle keys are lost or missing the Vehicle Electrical System Control Module -**J519** will need to be replaced to create a new identity and to program replacement keys to the vehicle.

## Service

Considering both/all original keys are missing, the Vehicle Electrical System Control Module -**J519** must also be replaced at the time of pairing of the new replacement keys in order to create new identity and to eliminate vehicle security vulnerabilities as a consequence of the missing keys.

## Warranty

Information Only. Not covered under warranty.

## Additional Information

© 2024 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.