

## GPOP - Issue Review System

**Part Number:** 68396134A\$

**Part Description:** TRANSFER CASE

**Issue Description:** Transfer case BW44-47 If fluid leak is present between the transfer case and the rear driveshaft on a 4WD vehicle the Output Shaft Seal - sub component parts should be considered in lieu of entire transfer case or driveshaft replacement. In the case of major damage to components, contact StarCenter and/or proceed with replacements as necessary.