



Service Bulletin

Bulletin No.: 24-NA-083

Date: September, 2024

INFORMATION

Subject: EV Charge Inlet Dust Cover Replacement Information

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	LYRIQ	2023	2024	-	-	All	All
Chevrolet	Silverado EV	2024	2024	-	-		

Involved Region or Country	North America
Condition	Some customers may comment on a missing or damaged HV charger port dust cover and tether.
Cause	The dust cover and tether are now released separately for Service.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Dust cover Part Number 24059685 is for Type 1 charger inlets used in North America (and other regions) but not all regions GM sells in.

Please review the GM Electronic Parts Catalog for proper use and Part Numbers.

Version	1
Modified	Released September 05, 2024

