



Bulletin No.: PIC6570

Published date: 09/3/2024

Preliminary Information

PIC6570 Center Console Spring Loaded Release Button - Part Ordering Instructions and Service Procedure

Models


Brand: Chevrolet **Model:** Corvette **Model Years:** 2023 - 2024 **VIN:** All **Engine:** All **Transmissions:** All

Chevrolet Corvette 2023 - 2024 All All All All

Involved Region or Country	North America
Additional RPO	
Condition	Some customers may find the center console button is not retained and sticks outside of the lid, or the button may become stuck in the fully depressed condition.
Concern	This concern is the result of a parts quality condition.

Correction:

If this concern is encountered, dealership technicians are to order a center console button from the Warranty Parts Center using the following form, which can be found on the GM Global Connect web site. It can be found under the "Service" tab. Once on that page, locate and select the icon for "Service Forms". Then, once that page opens, make certain the "General Information" tab is highlighted at the top of the page. Scroll down the list to find the selection titled, "WPC - Temporary Service Part (TSP) Request Form". This form is currently located on page 2. This form, as seen below, can then be filled out and copied. For the field titled "Part Requested (WPC#)", enter #WPC888 as indicated by the red arrow below.



Paste the completed form into a brand new e-mail and send it to the Warranty Parts Center (WPC) at the following address: warrantypartscenterusa@gm.com

They will ship a newly designed part to the dealership upon receipt of this completed form.

Once the part has arrived at the dealership, follow the instructions below to replace the component:

1) Open the console lid. Then, insert a trim tool behind the button assembly as shown in the first picture below. Pry on it gently to pop the button out of the center console as seen in the second photo below. If the button is stuck in when the vehicle arrives, pry the button out with the trim tool to allow the lid to open first.





- 2) If the spring comes out with the button assembly, this step may be skipped. If the button comes out of the console, but the spring remains, reach in and retrieve the spring with a small hook tool or a small pair of needle nose pliers.**

- 3) Transfer the parts from the old assembly to the new console button that was just shipped to the dealership, as seen in the photo below. Then, install the spring onto this new assembly.**



4) Insert the completed button assembly back into the console, and push it in until it is retained in place.

5) Operate the center console lid several times to make sure it functions correctly.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
1086878	Replace Center Console Button	0.3 Hrs.

Version History

Version	1
Modified	09/03/2024 - Created on.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.