



Service Bulletin

Bulletin No.: 23-NA-226

Date: September, 2024

INFORMATION

Subject: Information on Rear License Plate Installation


Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox EV	2024	2025	—	—	—	—

Involved Region or Country	North America, Brazil, Chile, Colombia, Ecuador, Uruguay, Israel, Palestine, GM Korea Company
Condition	As part of the Pre-Delivery Inspection (PDI), dealers may have concerns on how to properly install the rear license plate to the rear fascia.
Information	This bulletin provides details on how to effectively install the rear license plate.
Correction	Refer to the Service Procedure below.

Service Procedure

Important: Service agents must comply with all International, Federal, State, Provincial, and/or Local laws applicable to the activities it performs under this bulletin, including but not limited to handling, deploying, preparing, classifying, packaging, marking, labeling, and shipping dangerous goods. In the event of a conflict between the procedures set forth in this bulletin and the laws that apply to your dealership, you must follow those applicable laws.

Important: This technical service bulletin (TSB) can only be completed by certified repair facilities who have met all specific training, tool and equipment requirements pertaining to the vehicle Brand and Model serviced. Repairs must be performed by a technician who has successfully completed the required training.



6506314

1. Drill a 3/16" hole prior to the plate installation for U.S., Mexico, and Canada. The visual above shows the 4 locations to drill into on the rear fascia.

Note: For other regions, drill a 3/16" hole as required.

2. The plate screws will be provided in the vehicle. Install the license plate as appropriate.

Version	2
Modified	Released December 21, 2023 Revised September 20, 2024 – Added the 2025 Model Year.