



Bulletin No.: PIP4723J

Published date: 09/25/2024

Preliminary Information

PIP4723J Website for AFIT - TPM - GR8 - MIT and PICO Scope Updates

Models

Brand:	Model:	Model Years:	VIN:	Engine:	Transmissions:
			from to		
All	All	1995 - 2025	All All	All	All

Supersession Statement

This PI was superseded to include model year 2025 vehicles and update procedure for accessing website Please discard PIP4723H.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.


Condition / Concern

The process for reaching the GM Tools site has changed.

This website can now be accessed through the Global Connect home screen by selecting the "APP Center" tab then selecting "Dealer Equipment and Special Tools"

To access software downloads: From the home screen of the Special Tools and Equipment site, select the "Additional Resources" dropdown tab and select "Software", then select the tool to be updated from the list.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

 GM Global Brands

© 2024 General Motors. All Rights Reserved.