



Technical Service Bulletin

19 Cooling system: radiator fan control P048000/P048100

19 24 67 2075348/1 September 23, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, S4, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, Q5, Q5 Sportback, SQ5, SQ5 Sportback, Q7, SQ7, Q8, and SQ8	2021 – 2024	All	Not Applicable

Condition

Customer statement:

- The customer complains that the exhaust emissions warning lamp lights up, or the warning lamp for coolant temperature/ low coolant level lights up.

and/or

- Fan runs continuously.

Workshop findings:

The fan(s) run(s) “constantly”.

The following DTC or DTCs, and symptom code(s) is/are logged in the *Engine Control Unit -J623-*, (address word 0001):

- P048000** Cooling Fan 1 Control Circuit

and/or (depending on equipment)

- P048100** Cooling Fan 2 Control Circuit

Technical Background 1

In very rare cases, an open circuit in the wiring may occur. As a result, the radiator fan may be identified as a component that potentially causes damage.

Production Solution

Not applicable.



Technical Service Bulletin

Service

If the workshop findings above are confirmed, proceed as follows:

- Switch on ignition so that main relay is activated.
- Unplug the connector to the fan and check the voltage supply on the control wire 87 while it is under load.

If this is okay,

- The ignition can be switched off.
- Check the PWM wire for an open circuit between the connector from the engine control unit and the connector from the fan.

If this is okay, please perform Guided Fault Finding.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9713		
Damage Code:	0015		
Labor Operations:	Check electric fan	1908 0199	Bill according to time required
	Check engine wiring harness (if required)	9713 0199	Bill according to time required
	Repair wiring harness (depending on number of wires)	9709 41xx	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2075343/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2075348**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property



Technical Service Bulletin

rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.