

# V O L V O

## Volvo Car USA LLC

## Technical Journal

Technical Journal Title Difficulty clearing SODx DTCs		Ref. No. TJ 37048.1.0	
Issuer (Dept.) Technical Service		Issue Date 8/22/24	Status Date 9/4/24
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3872	
Function Description Collision avoidance		Page Page 1 of 2	

### DESCRIPTION:

If there are difficulties with clearing SODX DTCs using normal procedures, follow the advice under "Service".

DTC = Diagnostic Trouble Code

SODX (SODL/ SODR) = Side Obstacle Detection Control Module Left/ Right

### CSC Customer Symptom Codes

Code	Description
XR	Blind spot information system (BLIS)/Does not work
KS	Front/rear park assist/Does not work
48	Parking assistance/Parking Assist Pilot (PAP) does not work

### DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
SODR	C106057	Permanent
SODL	C106057	Permanent

### Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-9999		-	201835-999952
225							2019-9999		-	201817-999952
227							2019-9999		-	201817-999952
235							2020-9999		-	201920-999952
236							2020-9999		-	201920-999952
238							2020-9999		-	201920-999952
246							2020-9999		-	201920-999952
256							2020-9999		-	201920-999952
536							2018-9999		-	201746-999952
539							2018-9999		-	201746-999952

## Technical Journal 37048.1.0

---

### **SERVICE:**

To be able to clear the DTCs, put the car in usage mode “**Driving**” and continue the erasing process.

### **Warranty claim info:**

Information only. No warranty claim is accepted for this TJ.

### **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support needed”, use function group 3872.