

Diagnostic Sheet

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

Grecale –Axle Shaft Clicking Noise - Tech Tip

ATTENTION! This bulletin supersedes MAS004235 BOL 24-25 released on June 10, 2024, Please discard/remove all copies of the previous bulletin.

DATE: October 24, 2024

This Diagnostic Sheet serves as a guide and provides additional diagnostic info for possible axle shaft noise.

MODELS: M182 Grecale ICE ONLY (All MY). **Not applicable to BEV versions.**

CONCERN: Front/rear clicking noise while maneuvering the vehicle.

1. Remove the M24 axle nut (Pic.1) and thoroughly clean the grooves and hub thread with brake cleaner (Pic. 2).
2. Apply Molykote copper paste as illustrated – (Pic.3).
3. Replace the axle nut (component #12 in spare parts table 03.22-2 FRONT WHEELS TRANSMISSION).
4. Torque the axle shaft nut to specifications in the workshop manual.



Picture 1



Picture 2



Picture 3

In case of repeated concern, open a BOL as "Support Request" and provide a video of the noise and details of any additional activity done.

Please do not hesitate to contact us with any questions you may have.

Kind regards,

TECHNICAL SERVICE OPERATIONS