



# Technical Service Bulletin

## 92 Q8 e-tron washer fluid reservoir leaking

92 24 41 2075757/1 October 28, 2024.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron, and e-tron Sportback	2021 – 2023	All	Not Applicable
Q8 e-tron, SQ8 e-tron, Q8 Sportback e-tron, and SQ8 Sportback e-tron	2024 – 2025		

### Condition

#### Customer states:


Washer fluid reservoir leaking.

#### Workshop findings:

Filler connection not fitted correctly.

### Technical Background 1

Filler hose not fitted correctly.



*Figure 1. Filler hose not fitted correctly.*



# Technical Service Bulletin

---

## Production Solution

Optimized process.

## Service

1. Remove filler connection for washer fluid as specified in repair instructions.



*Figure 2. Removing filler connection.*



# Technical Service Bulletin

---

2. Pull filler neck out of washer fluid reservoir.



**Figure 3.** Detaching filler connection.

3. Check whether seal (8T0955465A) is OK and replace if necessary.

Assembly is performed in reverse sequence. Ensure that seal is not squeezed when fitting filler connection.

## Warranty

<b>Claim Type:</b>	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
<b>Service Number:</b>	9260		
<b>Damage Code:</b>	0050		
<b>Labor Operations:</b>	Remove and install filler connection for washer fluid reservoir	9260 1999	20 TU



# Technical Service Bulletin

---

	Check filler connection	9260 0199	5 TU
	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB 2075757/1		

All warranty claims submitted for payment must be in accordance with the Audi Warranty Policies and Procedures Manual. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2075757**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.