

WRJ0 Stop Delivery - Replacing the heating element for the left and right front seat and backrest

WRJ0 Stop Delivery - Replacing the heating element for the left and right front seat and backrest

ID Number	WRJ0
Models	911 (992)
Model Years	2022
VIN List	Attached below
Number of Affected Vehicles	7
Issue Description	<p>There is a possibility that the heating elements in the front seats and front backrests of the affected vehicles have not been manufactured to specification.</p> <p>As a result, when the seat heating is activated, there may be increased heat development at certain points, which may result in a risk of injury or damage to the seat cover.</p> <p>For this reason, the heating elements on the front seats and backrests must be replaced before the vehicle is delivered to the customer.</p>
What should Porsche Centers do?	<p>Please carry out the measure before delivery to the customer.</p> <p>As of the time of this posting (10/31/24) the remedy is immediately available.</p>
TI Number	No. 101-24

Attachments

- [1. PVMS VIN_List_Report_WRJ0_2024-10-31.XLSX](#)