

# WRL6 Workshop Campaign with customer letter –Check tires on front axle and replace if necessary

## WRL6 Workshop Campaign with customer letter -Check tires on front axle and replace if necessary

ID Number	WRL6
Model(s)	Boxster / Cayman 982
Model Year(s)	2023 - 2024
VIN List	Attached
Number of Affected VINs	8
Issue Description	There is the possibility that tires from different manufacturers have been installed on the front and rear axles of the affected vehicles. If this is the case, there may be restrictions on driving stability. For this reason, the tire manufacturer must check the tires on the front axle and replace the tires on the front axle depending on the test result.
What Dealers Should Do	Please arrange for this action to be performed immediately on the affected vehicles
TI	<a href="#">121-24</a>
Customer Letter	To be posted at a later date

## Required parts

Designation	Quantity/vehicle	Parts return*
2 tires on front axle*	1 piece	No

\*For warranty processing, enter the Part No. WRL60000001 with the designation "Tires" as an additional part in the warranty claim; cost as per invoice. Please document a copy of the invoice for this in the warranty claim. The required tires must be procured in line with the usual market processes. Procure tires according to the release list.

Please note: Further use of the removed tires is prohibited.

Designation	Quantity/vehicle
-------------	------------------

WRL6 Workshop Campaign with customer letter –Check tires on front axle and replace if necessary

Expendable items\*\* 1 piece

- Mounting paste
- Balance stick-on weights (5 - 90 grams as required)
- Tire disposal

## Warranty processing

Validity:

This workshop campaign will be carried out up to 01/08/2029 and will be closed by the specified date. Please note that warranty claims can only be processed up to this date.

### Scope 1:

Damage number WRL6 66 000  
Repair Code 1  
Labor time 0 TU

### Scope 2:

Damage number WRL6 66 000  
Repair Code 1  
Labor time 27 TU

### Scope 3:

Damage number WRL6 66 000  
Repair Code 2  
Labor time 106 TU

### Scope 4:

Damage number WRL6 66 000  
Repair Code 2  
Labor time 51 TU

### Scope 5:

Damage number WRL6 66 000  
Repair Code 2  
Labor time 128 TU

### Scope 6:

Damage number WRL6 66 000  
Repair Code 2  
Labour time 75 TU

WRL6 Workshop Campaign with customer letter –Check tires on front axle and replace if necessary

Please enter the campaign carried out, except for scope 1, in the Warranty and Maintenance logbook for the vehicle.

---

## **Attachments**

1. [WRL6 Campaign VIN Lists V2 10.02.2024 HT.xlsx](#)