

<b>Reference</b>	SSM76196
<b>Models</b>	New Range Rover / L460 New Range Rover Sport / L461
<b>Title</b>	22-24MY L460 L461 Loss passive start function
<b>Category</b>	Body
<b>Last modified</b>	11-Oct-2024 00:00:00
<b>Symptom</b>	112000 Latches/Locks & Security
<b>Content</b>	<p><u>Issue:</u> Passive start function not available, press of lock or unlock buttons required to restore function.</p> <p><u>Cause:</u> Outdated RFA Software level F188 L8B2-14C104-AV causing vehicle to ignore passive key when left in unlocked vehicle for extended period longer than 20 minutes.</p> <p><u>Action:</u> Perform RFA module software update to latest level to address this concern.</p> <p><small>anBhdHRicnM7MjAyNC0xMS0wNiQxNzoxNToyNy4zOTVhOzEzNi4yMjYyODEuMTA4Ow==</small></p>