

Reference	SSM76208
Models	Defender / L663 Discovery / L462 New Range Rover / L460 New Range Rover Sport / L461
Title	Oil leak from rear of the vehicle
Category	Driveline
Last modified	25-Oct-2024 00:00:00
Symptom	510000 Fluid Concerns
Attachments	Attachment-1.png (Attachment-1.png)
Content	<p>Model / Model Year / Derivative</p> <p>Range Rover Sport / 23-24MY / All Range Rover / 22-24MY / All Defender / 22-24MY / All Discovery / 21-24MY / All</p> <p>Situation:</p> <p>JLR Engineering investigations have found customers reporting oil leaks from the rear of the vehicle.</p> <p>Cause:</p> <p>Damage to the rear differential pinion seal.</p> <p>Action:</p> <p>Refer to the service request below.</p> <p>Service Request:</p> <p>If you have a rear differential oil leak from the highlighted area shown in 'Attachment 1', then do not repair the vehicle, hold the vehicle and raise a Technical Assistance (TA) to PTS_800. Attach photos to the TA to show the differential oil leak.</p> <p>The PTS_800 engineering team will provide further guidance, and may initiate a Parts Return Request (PRR) in order to complete engineering analysis on the rear differential. For this reason it is important that the rear differential pinion seal is not removed or disturbed.</p> <p>(Ref 000382155)</p>